VCDS
Windows Based VAG/VAS Emulator Running on Windows 10 x64
VCDS Version: Release 16.8.3(x64) Data version: 20161010 DS267.0
www.Ross-Tech.com

Dealer/Shop Name: Arbormotion
Workshop Code: 000 12345 000000

Self-Diagnosis Log
Monday,28,November,2016,10:04:55:37099

VIN: License Plate:
Mileage: Repair Order:

Gateway Installation List: 1K0 907 530 E

00-Steering Angle Sensor -- Status: OK 0000
01-Engine -- Status: Malfunction 0010
02-Auto Trans -- Status: Malfunction 0010
03-ABS Brakes -- Status: Sporadic communication error 1000
08-Auto HVAC -- Status: OK 0000
09-Cent. Elect. -- Status: Malfunction 0010
0F-Digital Radio -- Status: Malfunction 0010
15-Airbags -- Status: Malfunction 0010
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: Malfunction 0010
1C-Position Sensing -- Status: Malfunction 0010
25-Immobilizer -- Status: Malfunction 0010
36-Seat Mem. Drvr -- Status: OK 0000
42-Door Elect, Driver -- Status: OK 0000
44-Steering Assist -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: OK 0000
52-Door Elect, Pass. -- Status: OK 0000
56-Radio -- Status: Malfunction 0010
62-Door, Rear Left -- Status: Sporadic communication error 1000
72-Door, Rear Right -- Status: Sporadic communication error 1000

Scanned by CamScanner

VCDS
Windows Based VAG/VAS Emulator Running on Windows 10 x64
Version: Release 16.8.3
www.Ross-Tech.com

Dealer/Shop Name: Arbormotion
Workshop Code: 000 12345

Diagnostic Trouble Code Report
Monday,28,November,2016,10:09:01:37099

VIN: License Plate:
Mileage: Repair Order:

Control Module Part Number: 06A 906 032 QE HW: Hardware No G 6656
Component and/or Version: 2.5l R5/4V
Software Coding: 0000003
Work Shop Code: WSC 97000 444 59318
VCID: 71E934326839F1CA43-8024

7 Faults Found:
17978 - Engine Start Blocked by Immobilizer
P1570 - 008 - - Intermittent
18711 - Leak in Air Intake System
P2279 - 008 - - Intermittent
[illegible]unication with ABS Brake Control Module
[illegible]ntermittent [illegible]l Module

Scanned by CamScanner

VCDS
Windows Based VAG/VAS Emulator Running on Windows 10 x64
Version: Release 16.8.3
www.Ross-Tech.com

Dealer/Shop Name: Arbormotion
Workshop Code: 000 12345

Diagnostic Trouble Code Report
Monday,28,November,2016,10:05:39:37099

VIN: License Plate:
Mileage: Repair Order:

Electrics mod. under dash

Control Module Part Number: 1K0 937 049 C HW: 1K0 937 049 C*
Component and/or Version: Bordnetz-SG H34 0803
Software Coding: F4058E0240041800001400000014000000207703 5C
Work Shop Code: WSC 00000 000 00000
VCID: 2F6DF24ABE8DA73A15-807A
Additional Info: Fehler Lin-Slave 01 Fehler Lin-Slave 02

1 Fault Found:
02071 - Local Databus
004 - No Signal/Communication

St. Column mod
1K0 953 549 AC

Scanned by CamScanner