Hotline Archive	***With Service Manuals diagrams, components, TSBs, and R&R procedures***	<< Back Bookmark Print Preview ▼ Print ▼
Number:	202535	
Vehicle Application:	2001 Ram 2500 5.9	2001 Ram 2500 Pickup 5.9
Customer Concern:	Cam Angle Sensor (CMP) code on this diesel motor. Trouble code P0341.	
Average Reported Mileage:	86000	
Tests/Procedures:	1. Check the Cam Angle Sensor (CMP) signal with a lab scope. 2. Next check the camshaft end play.	
Author:	Michael Brown	
Diagnostic Codes	P0341	

Potential Causes ***With Service Manuals diagrams, components, TSBs, and R&R procedures***

Bearing
Cam Angle (CMP) Sensor
Wiring Diagrams
Remove and Replace
CAMSHAFT POSITION SENSOR (INSTALLATION) (8 - ELECTRICAL) (IGNITION CONTROL)
CAMSHAFT POSITION SENSOR (INSTALLATION) (CRANKSHAFT POSITION SENSOR) (FUEL INJECTION) (5.9L CUMMINS TURBO DIESEL) (14 - FUEL SYSTEM)
CAMSHAFT POSITION SENSOR (REMOVAL) (8 - ELECTRICAL) (IGNITION CONTROL)

CAMSHAFT POSITION SENSOR (REM... << Back Forward >> Bookmark Print Preview Print Close



CAMSHAFT POSITION SENSOR (REMOVAL) (CRANKSHAFT POSITION SENSOR) (FUEL INJECTION) (5.9L CUMMINS TURBO DIESEL) (14 - FUEL SYSTEM)

Back To Top < Previous 10 | Next 10 > **Results: 1 - 4 of 4** Show All

Specifications/Capacities
Component Locations
8.1 CONTROL MODULES AND IPM (POWERTRAINGAS)

Back To Top < Previous 10 | Next 10 > **Results: 1 - 1 of 1** Show All

Pin-Out/Connector Views
TSBs
Other
Camshaft

What Fixed It ?

Please describe what was done to fix the vehicle you were working on. 300 characters left Posting Guidelines
Example 1: **Replaced fuel pump**
Example 2: **Cleaned Throttle Body**

If the problem you were fixing is **NOT** the same as the problem described in the "Customer Concern" please use the Post Fix link to share your fix.

Still need help? Click here to access the Hotline Call Request Form to schedule a call from one of our Carline Specialists.

Comments may be posted publicly with your username. Submit

Copyright 2001 - 2015 Identifix, Inc. All rights reserved. Use of this online service is subject to Terms of Use