Panoramic Roof Panel Blind

Removal

1. **WARNING: Before beginning any service procedure in this section, refer to Safety nings in section 100-00 General Information. Failure to follow this instruction may result in serious personal injury.**

   Refer to: Health and Safety Precautions (100-00 General Information, Description and Operation).

2. Refer to: Headliner (501-05 Interior Trim and Ornamentation, Removal and Installation).

3.



Installation

1. To install, reverse the removal procedure.

2. Refer to: Panoramic Roof Panel Blind Initialization (501-05 Interior Trim and Ornamentation, General Procedures).

Copyright © 2016 Ford Motor Company